


PL259 Connector Assembly



INSRUCTIONS

Strip coax as illustrated then feed through the center of the PL259 screw tightly up the center then solder the top of the connector.

NOTE

This is a guide that is based on the current supply of connectors from overseas and should be a guide only, as the dimensions will vary from supply to supply.....