


BNC Crimp connector



INSRUCTIONS

Slide onto coax the BNC crimp sleeve then Strip coax as illustrated First strip the 15mm off the black outer jacket next strip off the outer braid leaving a maximum off 6mm of braid then strip 4mm off the centre plastic dielectric, crimp pin then slide connector on then move the crimp sleeve then crimp sleeve so that the braid is secured between the connector and the crimp sleeve